



Radio Dispatch Engineering Group

ADHB-4 Gen 2 Version 1.500 Engineering Release Notes

Notice:

The content in this document represents the current view of Bosch Security Systems as of the date of publication. Because Bosch Security Systems responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Bosch Security Systems. Bosch Security Systems cannot guarantee the accuracy of any information presented after the date of publication.

Brand Names mentioned are the property of their respective companies.

Bosch Security Systems, LLC. All rights reserved.

F01U376921 – Revision 5

September 15, 2025

Table of Contents

Revision History	2
Overview	2
Important	2
New Features	2
Feature improvements and known issues fixed in this release	2
Version 1.500	2
Compatibility	3
C-Soft Application	3
Telex System Manager	3
Installation and Upgrade	3

Revision History

Revision	Date	Author	Description
01	05/17/19	Radio Dispatch Engineering	Firmware Version 1.000 Release
02	12/20/19	Radio Dispatch Engineering	Firmware Version 1.100 Release
03	03/25/22	Radio Dispatch Engineering	Firmware Version 1.200 Release
04	07/25/24	Radio Dispatch Engineering	Firmware Version 1.300 Release
05	09/15/25	Radio Dispatch Engineering	Firmware Version 1.500 Release

Overview

This document contains the release notes for the ADHB-4 Gen 2's firmware version 1.500. The release notes include all of the changes and fixes since official release version 1.300. Cross application compatibilities are outlined in this document.

Important

After upgrading from a previous firmware revision to version 1.300 or newer, the unit will reboot and begin the process of updating system components. During the update process, the unit will display "Firmware Updating". This update process takes approximately 1 minute, after which the unit will self-reboot and operate normally. **Ensure that the unit completes the update cycle and boots normally before removing power from the unit.**

After the ADHB-4 Gen 2 firmware has been upgraded to version 1.500 or newer, the firmware cannot be reverted to any previous version (1.100 or earlier). Any attempt to downgrade the firmware version via TSM will be refused by the ADHB-4 Gen 2.

New Features

Feature improvements and known issues fixed in this release.

Version 1.500

- Updated the Copyright to 2025.
- Updated JQUERY library version to 3.7.1
- Updated JQUERY_UI library version to 1.14.1

Note: Versions 1.4 were not released.



Radio Dispatch

ADHB-4 Gen 2 Version 1.500 Release Notes

Compatibility

C-Soft Application

- Version 7.600+

Telex System Manager

- Version 2.600+ - Necessary for programming parameters.
- Version 2.500+ - Necessary firmware upgrades.

Installation and Upgrade

Please use Telex System Manager 2.500 or newer to upgrade the firmware.