



TELEX

Radio Dispatch

Radio Dispatch Engineering Group

System Manager 1.400 Engineering Release Notes

Notice:

The content in this document represents the current view of Bosch Security Systems as of the date of publication. Because Bosch Security Systems responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Bosch Security Systems. Bosch Security Systems cannot guarantee the accuracy of any information presented after the date of publication.

Bosch Security Systems. All rights reserved

Revision G

October 18, 2010

Table of Contents

1. Revision History	1
2. Overview.....	1
3. New Features	1
4. Improved Features and Fixed Issues	1
5. Compatibility.....	1
6. Installation and Upgrade.....	2

1. Revision History

Revision	Date	Author	Description
A	7/30/2008	Radio Dispatch Engineering	Initial draft System Manager Version 1.100
B	08/03/2009	Radio Dispatch Engineering	Updated System Manager Version 1.200
C	01/06/2010	Radio Dispatch Engineering	Updated System Manager Beta Version 1.205
D	03/30/2010	Radio Dispatch Engineering	Updated System Manager Version 1.300
E	10/01/2010	Radio Dispatch Engineering	Updated System Manager Version 1.302
F	10/07/2010	Radio Dispatch Engineering	Updated System Manager Version 1.303
G	10/18/2010	Radio Dispatch Engineering	Updated System Manager Version 1.400

2. Overview

This is the release notes for Telex System Manager firmware/software. This release contains new features, improved features, and fixed issues. The release notes include all of the changes and fixes since official release Version 1.300

3. New Features

Version 1.400

- Added Serial over IP setup fields to IP-223 configuration.

4. Improved Features and Fixed Issues

Version 1.400

- Fixed issue with firmware update tool tab order.
- ADHB-4 Configuration
 - o Added ADHB-4 Serial Number and Checksum fields.
 - o Added NENA option in Common Record setup.
 - o Updated ADHB-4 Microphone Input Gain fields to accept values from -12 to 20 dB.
- IP-223 Configuration
 - o Added TDI Gain, Ring Setup, Monitor, RCP DTMF Decode, and Freq Update w/ PTT fields.
 - o Allowed #,*,A,B,C,D characters to be entered into Crosspatch and DTMF signaling fields.
 - o Allowed Digital Output field to accept a value of 128.
 - o Fixed issue which caused the IP-223's web server to be disabled when enabling the Freq Update w/ PTT option on Line 2.
 - o FleetSync and MDC Encode can now be enabled in Tone Mode.
 - o Serial Port mode is now set to Serial Over IP mode when Serial Over IP is enabled on a line.
 - o Serial Over IP can no longer be enabled in iDEN or Tetra mode.

5. Compatibility

- System Manager 1.400 has all the capabilities and compatibility of version 1.200. Only new capabilities and fixes to existing features were made.

6. Installation and Upgrade

- To install Telex System Manager 1.400
 - o If the .NET 2.0 framework or greater is not installed, first install using either through the Microsoft update.
 - o Run setup.exe and follow the prompts.