



TELEX[®]

RADIO DISPATCH PRODUCTS

Radio Dispatch Engineering Group

Network Recorder Monitor Version 1.100 Release Notes

Notice:

The content in this document represents the current view of Telex® as of the date of publication. Because Telex® responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Telex®. Telex® cannot guarantee the accuracy of any information presented after the date of publication.

Telex®. All rights reserved

June 19, 2009 – Revision A

Table of Contents

1. Revision History	1
2. Overview	1
3. New Features	1
4. Feature improvements and known issues fixed in this release	1
5. Installation and Upgrade	1

1. Revision History

Revision	Date	Author	Description
A	6/19/2009	Software Engineering Group	Initial draft

2. Overview

This release contains improvements and enhancements, which are listed in the new features section of this document, as well as fixes to reported problems from previous releases (1.000).

3. New Features

If the main window is minimized and an error or warning message is received from the Network Recorder, the Network Recorder Monitor task bar application icon will “flash” to indicate a problem with Network Recorder software. If the Network Recorder software is “Hidden” instead of minimized when an error or warning comes in, the Network Recorder Monitor main window will “show or unhide”.

4. Feature improvements and known issues fixed in this release

Messaging handling was added to detect hard drive errors from the Network Recorder.

5. Installation and Upgrade

- Install “Telex Network Recorder Monitor” Software. Do not remove previous version via add/remove programs wizard.