



# **TELEX<sup>®</sup>**

## **RADIO DISPATCH PRODUCTS**

### **Radio Dispatch Engineering Group**

#### **IP-1616 BETA Release Version 4.101 Engineering Release Notes**

---

#### **Notice:**

The content in this document represents the current view of Telex® as of the date of publication. Because Telex® responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Telex®. Telex® cannot guarantee the accuracy of any information presented after the date of publication.

Telex®. All rights reserved

---

October 30, 2008 – Revision B

---

**Table of Contents**

<b>1. Revision History .....</b>	<b>1</b>
<b>2. Overview .....</b>	<b>1</b>
<b>3. New Features .....</b>	<b>1</b>
Version 4.101 .....	1
<b>4. Feature improvements and known issues fixed in this release .....</b>	<b>1</b>
Version 4.101 .....	1
<b>5. Compatibility .....</b>	<b>1</b>
Version 4.101 .....	1
<b>6. Installation and Upgrade .....</b>	<b>1</b>
Version 4.101 .....	1

---

## 1. Revision History

Revision	Date	Author	Description
A	10/30/2008	Radio Dispatch Engineering Group	Updated IP-1616 Version 4.101

## 2. Overview

This is the release notes for IP-1616 release version 4.101. This release contains new features, improved features, and fixed issues. The release notes include all of the changes and fixes since official release Version 4.100.

**NOTE:** Please note that Telex FTP Application is no longer used for system upgrade. The Telex Firmware Binary (tfb) is the new firmware format instead of the bin file. User will need to use Telex System Manager Application to save, clone parameters configuration and upgrade firmware.

## 3. New Features

### Version 4.101

- Kill Lines on Crosspatch – When disable, it allows the crosspatch audio to be heard outside of the “Cross Patch 1” menu.
- Crosspatch Audio Selection – This feature allows crosspatch audio to be play either on the SEL or UNSEL speaker.
- CRP PTT Mode Selection – This option will allow any PTT Key to key up Crosspatch lines while in “Cross Patch 1” menu.
- Restore Factory Default – This option will restore all the console parameters the factory default.

## 4. Feature improvements and known issues fixed in this release

### Version 4.101

- Fixed: Record Configuration failure in TSM
- Fixed: VU bar does not work correctly when receive RX audio
- Fixed: When send FleetSync status for long period of time, system crashed

## 5. Compatibility

### Version 4.101

- NA

## 6. Installation and Upgrade

### Version 4.101

- Please use TSM Version 1.0.0.9 or newer and TELEX VEGA VoIP Software Instructions to upgrade the firmware