



TELEX

Radio Dispatch

Radio Dispatch Engineering Group

Telex System Manager 3.200 Engineering Release Notes

Notice:

The content in this document represents the current view of Bosch Security Systems as of the date of publication. Because Bosch Security Systems responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Bosch Security Systems. Bosch Security Systems cannot guarantee the accuracy of any information presented after the date of publication.

Bosch Security Systems. All rights reserved

F01U306256 - Revision 16

Oct 19, 2022

Table of Contents

1. Revision History	1
2. Overview	1
3. New Features	1
4. Improved Features and Fixed Issues	2
5. Known Issues	2
6. Compatibility	2
7. Installation and Upgrade	2

1. Revision History

Revision	Date	Author	Description
A	07/30/2008	Radio Dispatch Engineering	Initial draft System Manager Version 1.100
B	08/03/2009	Radio Dispatch Engineering	Updated System Manager Version 1.200
C	03/30/2010	Radio Dispatch Engineering	Updated System Manager Version 1.300
D	10/18/2010	Radio Dispatch Engineering	Updated System Manager Version 1.400
E	06/08/2012	Radio Dispatch Engineering	Updated System Manager Version 1.500
F	08/20/2014	Radio Dispatch Engineering	Updated System Manager Version 1.600
G	01/15/2015	Radio Dispatch Engineering	Updated System Manager Version 1.700
H	02/20/2015	Radio Dispatch Engineering	Updated System Manager Version 2.000
I	5/05/2016	Radio Dispatch Engineering	Updated System Manager Version 2.100
10	5/25/2017	Radio Dispatch Engineering	Updated System Manager Version 2.200
11	11/27/2017	Radio Dispatch Engineering	Updated System Manager Version 2.300
12	9/20/2018	Radio Dispatch Engineering	Updated System Manager Version 2.400
13	12/4/2019	Radio Dispatch Engineering	Updated System Manager Version 2.500
14	9/8/2021	Radio Dispatch Engineering	Updated System Manager Version 3.000
15	6/14/2022	Radio Dispatch Engineering	Updated System Manager Version 3.100
16	10/19/2022	Radio Dispatch Engineering	Updated System Manager Version 3.200

2. Overview

This is the release notes document for the Telex System Manager Version 3.200 software. This release contains new features, improved features, and fixed issues. The release notes include all of the changes and fixes since official release Version 3.000.

3. New Features

Version 3.200

- None

Version 3.100

- Added support for CMS licensing operations
- IP-3002, IP-3008, IP-3018, and C-Soft
 - Ethernet
 - Primary Adapter Interface
 - Added parameters to support CMS operation. This includes:
 - CMS Connection settings
 - 'Connect to CMS' checkbox
 - CMS Address
 - CMS Control Port
 - Design Settings
 - Use CMS for Design Management
 - Login Behavior
 - Default Username
 - Default Password
 - Failover Behavior
 - Show Local Designs
 - Logging

- Added additional retrievable log types, including Console Configuration Tool and Console Launcher
- IP-224
 - Added CMS Connection address fields
 - Added SRTP Encryption setting.

4. Improved Features and Fixed Issues

Version 3.200

- IP-224
 - Fixed crash when trying to read from an IP-224 or open an IP-224 configuration file from a version prior to IP-224 3.000.
- IP-30XX Firmware Update
 - Added mechanism to limit IP-30XX to only allow installation of new versions greater than or equal to the version already installed on the device. This was added to address some backward compatibility problems with IP-30XX firmware, avoiding the potential for soft bricking the device.

5. Known Issues

- IP-1616 v4.100 does not support changing the Console Name or Base IP Setup parameters via System Manager.
- IP-2002 v4.100 does not support changing the Console Name or Base IP Setup parameters via System Manager.

6. Compatibility

- Operating System
 - Telex System Manager is compatible with Windows 10 or newer.
 - If using Windows 7, TSM will likely fail to communicate with C-Soft or IP-30XX devices due to specific security options not being available by default in Windows 7.
- System Manager v3.200 supports the following device firmware versions:

Device	Minimum Firmware/Software Version
ADHB-4	v3.600
ADHB-4 Gen 2	v1.100
C-Soft	v8.000
IP-1616	v4.100
IP-2002	v4.100
IP-223	v4.505
IP-224	v3.000
IP-30XX	v8.100

7. Installation and Upgrade

- To install Telex System Manager 3.200
 - If .NET framework 4.7.2 or greater is not installed, first install using either through Microsoft update.
 - Run setup.exe and follow the prompts.