Key 8 / 3/95



of Transportation Federal Aviation

**Administration** 

Small Airplane Directorate Chicago Aircraft Certification Office 2300 East Devon Avenue Des Plaines, IL 60018

Mr. Michael T. Syfko Telex Communications, Inc. 9600 Aldrich Avenue South Minneapolis, MN 55420

Dear Mr. Syfko:

This is in reply to your letter of July 11, 1995, requesting Technical Standard Order (TSO) Authorization for your Model AIR 3500(), P/N 300400-(), Pilot Headset with Boom Michrophone and Volume Controls.

The Statement of Conformance to TSO-C57a and -58a in your July 11, 1995 letter and the submitted data are accepted. You are authorized to identify your Model AIR 3500(), P/N 300400-(), Pilot Headset with Boom Michrophone and Volume Controls, with TSO-C57a and -C58a markings.

Your Quality Control System as defined in your Quality Control Manual, revised November 1989, is considered satisfactory for production of this equipment at your manufacturing facility located in Minneapolis, Minnesota.

In accordance with our agreement, we are returning the submitted data (except Item a) for your disposition:

Statement of Conformance in your letter dtd. 7/11/95, and а.

ь. Test Report No. 2510, AIR 3500 Pilot Headset, Telex P/N 30400-000, dtd. 7/11/95.

We acknowledge P/N 300400-000 as the first in a series.

Any design change made to this TSO'd item must be forwarded to this office as outlined in Federal Aviation Regulation (FAR) 21.611 with minor change submittal intervals not to exceed six months. Also, as recipient of this authorization, you are required to report any failure, malfunction, or defect relating to this authorization in accordance with the provisions of FAR 21.3.

If you have any questions regarding this authorization, contact Mr. Les Taylor, telephone (708) 294-7126.

Sincerely,

Lesheb. Jaylor

Carl F. Mittag Manager, Systems & Equipment Branch

Enclosure