



# TELEX

## *Radio Dispatch*

### Radio Dispatch Engineering Group

#### Telex System Manager 2.300 Engineering Release Notes

---

#### Notice:

The content in this document represents the current view of Bosch Security Systems as of the date of publication. Because Bosch Security Systems responds continually to changing market conditions, this document should not be interpreted as a commitment on the part of Bosch Security Systems. Bosch Security Systems cannot guarantee the accuracy of any information presented after the date of publication.

Bosch Security Systems. All rights reserved

---

F01U306256 - Revision 11

November 27, 2017

**Table of Contents**

1. Revision History .....	1
2. Overview .....	1
3. New Features .....	1
4. Improved Features and Fixed Issues .....	1
5. Known Issues .....	1
6. Compatibility .....	2
7. Installation and Upgrade .....	2

### 1. Revision History

Revision	Date	Author	Description
A	07/30/2008	Radio Dispatch Engineering	Initial draft System Manager Version 1.100
B	08/03/2009	Radio Dispatch Engineering	Updated System Manager Version 1.200
C	03/30/2010	Radio Dispatch Engineering	Updated System Manager Version 1.300
D	10/18/2010	Radio Dispatch Engineering	Updated System Manager Version 1.400
E	06/08/2012	Radio Dispatch Engineering	Updated System Manager Version 1.500
F	08/20/2014	Radio Dispatch Engineering	Updated System Manager Version 1.600
G	01/15/2015	Radio Dispatch Engineering	Updated System Manager Version 1.700
H	02/20/2015	Radio Dispatch Engineering	Updated System Manager Version 2.000
I	5/05/2016	Radio Dispatch Engineering	Updated System Manager Version 2.100
10	5/25/2017	Radio Dispatch Engineering	Updated System Manager Version 2.200
11	11/27/2017	Radio Dispatch Engineering	Updated System Manager Version 2.300

### 2. Overview

This is the release notes document for the Telex System Manager software. This release contains new features, improved features, and fixed issues. The release notes include all of the changes and fixes since official release Version 2.200.

### 3. New Features

#### Version 2.300

- IP-224:
  - Network Setup
    - Updated SNMP fields to SNMPv3:
      - Username
      - Auth Password
      - Privacy Password
      - Trap Target 1-3 Enable and IP Address
  - Additional Features
    - All prior features licenses consolidated to “Advanced Interface Option (Export)” or “Advanced Interface Option (North America)”
    - Updated page to display list of supported Serial Modes instead of enabled features.

### 4. Improved Features and Fixed Issues

#### Version 2.200

- Firmware Update
  - Added additional checks to properly detect a corrupted firmware file.

### 5. Known Issues

- IP-1616 v4.100 does not support changing the Console Name or Base IP Setup parameters via System Manager.
- IP-2002 v4.100 does not support changing the Console Name or Base IP Setup parameters via System Manager.

### 6. Compatibility

- System Manager v2.300 supports the following device firmware versions:

Device	Minimum Firmware Version
ADHB-4	v3.000
IP-1616	v4.100
IP-2002	v4.100
IP-223	v4.505
IP-224	v2.300

### 7. Installation and Upgrade

- To install Telex System Manager 2.300
  - If .NET 4.0 framework or greater is not installed, first install using either through Microsoft update.
  - Run setup.exe and follow the prompts.